Report Date: 14 Feb 2022

441-14G-3019 Troubleshoot Switches for Air Missile Defense (AMD) Operations Status: Approved

Security Classification: U - Unclassified

 $\textbf{Distribution Restriction:} \ \textit{Approved for public release; distribution is unlimited}.$

Destruction Notice: None

Foreign Disclosure: FD1 - This training product has been reviewed by the training developers in coordination with the United States Army Fires Center of Excellence G32, Fort Sill, Oklahoma

73503 foreign disclosure officer. This training product can be used to instruct international military students from all approved countries without restrictions.

Conditions: You are in a field/tactical environment, the Air Battle Management System (ABMS) has just been erected and your ABMS is experiencing some problems operating. Your supervisor has directed you to troubleshoot the Switch on your Air Battle Management System. The following is available: References: 1) ADSI Installation and Configuration Guide, ADSI User Guide, TM 11-7010-320-10, TM 11-7010-543-10-1, TM 11-7010-543-10-2, TB 11-5895-1887-13, TM 11-5895-1887-23&P, TM 11-5895-1887-10, TM 11-5895-1887-SAM, TM 11-7010-363-SAM, TacViewC2 User Guide, and TM 11-7010-363-SUM; 2) Equipment: Digital Computer Workstation, Air Missile Defense Workstation (AMDWS), Center Communication Operations: AN/TSQ-253(V)5, Workstation: Airspace Operation AN/FSQ-211A, and Air Defense System Integrator (ADSI): AN/MSQ-214. Some iterations of this task should be performed in MOPP 4.

Standards: Troubleshoot Switch on the Air Battle Management System (ABMS) IAW the steps and procedures in ADSI Installation and Configuration Guide, ADSI User Guide, TM 11-7010-320-10, TM 11-7010-543-10-1, TM 11-7010-543-10-2, TB 11-5895-1887-13, TM 11-5895-1887-23&P, TM 11-5895-1887-10, TM 11-5895-1887-SAM, TM 11-7010-363-SAM, TacViewC2 User Guide, TM 11-7010-363-SUM and Tactical Standing Operating procedures (TSOP), utilizing the GO/NO-GO criteria, without error, without causing injury to self or other personnel, without damage to equipment, with minimal damage to the environment and within the time prescribed by local command directives.

Special Conditions: None

Safety Risk: Low

MOPP 4: Sometimes

Task Statements

Cue: You have been directed by your supervisor to troubleshoot your switches inside your AMD Shelter.

None WARNING None CAUTION None

Remarks: None

Notes: All required Air Defense specific references and technical manuals will be provided by the local Air Defense Command.

Performance Steps

- 1. Verify fault is at the switch.
- 2. Check switch cables are seated properly (power and ethernet cables).
- 3. Check link lights of devices cabled into the switch for port activity.
- 4. Open HyperTerminal session to verify switch settings.
- 5. Issue show ip interface brief command to check interfaces.
 - a. Switch> enable.
 - b. Password: enablepassword.
 - c. Switch# show ip interface brief.

Note: If an interface used has administratively down shown under the Status column, issue the no shutdown command when in interface configuration mode for that interface.

- 6. Issue no shutdown command as required:
 - a. Switch# config terminal.
 - b. Switch (config#) interface ethernet0/0 / fastEthernet0/0 /Gigabitethernet0/0.

Note: Type in interface port to issue no shutdown command.

- c. Switch (config-if#) no shutdown.
- d. Switch (config-if#) exit.
- e. Switch (config#) exit.
- f. Switch#.
- 7. Issue ping command to test connectivity with devices on the network.
- 8. Reload switch configuration file.

Note: Refer to task 441-14G-2005 Configure Switches for AMD Operations.

9. Refer to Network Administrator for further guidance.

(Asterisks indicates a leader performance step.)

Evaluation Guidance: Score the Soldier GO if all steps are passed (P). Score the Soldier NO-GO if any step is failed (F). If the Soldier fails any step, show the soldier what he did wrong and how to do it correctly.

Evaluation Preparation: Ensure that all information, references, and equipment required to perform the task are available. Use the performance measures and the references to score the Soldier's performance. Brief the Soldier. Tell the Soldier what he is required to IAW the task conditions and standards.

PERFORMANCE MEASURES	GO	NO-GO	N/A
1. Verified fault is at the switch.			
2. Checked switch cables are seated properly (power and ethernet cables).			
3. Checked link lights of devices cabled into the switch for port activity.			
4. Opened HyperTerminal session to verify switch settings.			
5. Issued show ip interface brief command to check interfaces.			
6. Issued no shutdown command as required:			
7. Issued ping command to test connectivity with devices on the network.			
8. Reloaded switch configuration file.			
9. Referred to Network Administrator for further guidance.			

Supporting Reference(s):

Step Number	Reference ID	Reference Name	Required	Primary	Source Information
	200-3-v11.8-3-c	TacViewC2, User's Guide - Version 11.8	Yes	No	
	ADSI	ADSI USER MANUAL	Yes	No	
	TB- 11-5895-1887-13	TECHNICAL BULLETIN SOFTWARE USER MANUAL FOR SOFTWARE, TACTICAL AIRSPACE INTEGRATION SYSTEM (TAIS) SOFTWARE VERSION 12.0.2	Yes	No	
	TM 11-5895-1887-13	Technical Bulletin Software user Manual For Software, Tactical Airspace integration System (TAIS) Software Version 12.0.2	Yes	No	
	TM 11-5895-1887-23&P	FIELD MAINTENANCE MANUAL INCLUDING REPAIR PARTS AND SPECIAL TOOLS LIST FOR COMMAND SYSTEM, TACTICAL (TACTICAL AIRSPACE INTEGRATION SYSTEM) (TAIS) AN/TSQ-221A(V)1 (NSN 5895-01- 574-6798) (EIC 24B) AN/TSQ-221A(V)2	Yes	No	
	TM 11-5895-1887-SAM	SOFTWARE ADMINISTRATORS MANUAL FOR TAIS SOFTWARE ADMINISTRATORS MANUAL (SAM) VERSION 12.0.3 (NSN N/A) (EIC N/A)	Yes	No	
	TM 11-7010-320-10	OPERATOR MANUAL FOR FORWARD AREA AIR DEFENSE COMMAND, CONTROL AND INTELLIGENCE (FAAD C2I) SYSTEM, SYSTEM ADMINISTRATOR'S HANDBOOK (SOFTWARE VERSION 5.5C)	Yes	No	
	TM 11-7010-363-SAM	TECHNICAL MANUAL SOFTWARE ADMINISTRATORS MANUAL FOR AIR AND MISSILE DEFENSE WORKSTATION (AMDWS) VERSION 7.0.2.0	Yes	No	
	TM 11-7010-363-SUM	TECHNICAL MANUAL SOFTWARE USERS MANUAL FOR AIR AND MISSILE DEFENSE WORKSTATION (AMDWS) VERSION 7.0.2.0	Yes	No	
	TM 11-7010-543-10-1	OPERATOR MANUAL FOR FORWARD AREA AIR DEFENSE (FAAD)/COUNTER-ROCKET, ARTILLERY, AND MORTAR COMMAND AND CONTROL (C-RAM C2) SYSTEM SOFTWARE USER GUIDE FOR COMMUNICATION CONTROL SET SUBSYSTEMS	Yes	No	
	TM 11-7010-543-10-2	OPERATOR MANUAL FOR FORWARD AREA AIR DEFENSE (FAAD)/COUNTER-ROCKET, ARTILLERY, AND MORTAR COMMAND AND CONTROL (C-RAM C2) SYSTEM SOFTWARE USER GUIDE FOR COMMUNICATION CONTROL SET SUBSYSTEMS	Yes	No	
	TM 11-7010-544-10	OPERATOR MANUAL FOR FORWARD AREA AIR DEFENSE COMMAND, CONTROL AND INTELLIGENCE (FAAD C2I) SYSTEM SOFTWARE USER GUIDE FOR COUNTER-ROCKET, ARTILLERY AND MORTAR (C2-RAM) COMMAND AND CONTROL (C2) (SOFTWARE VERSION 5.5C-2.2-P1)	Yes	No	
	TSOP	TACTICAL STANDING OPERATING PROCEDURES.	Yes	Yes	

TADSS: None

Equipment Items (LIN):

LIN	Name
C77942	Center Communications Operations: AN/TSQ-253(4)

Materiel Items (NSN):

Step ID	NSN	LIN	Title	Qty
No materiel item	s specified			

Environment: Environmental protection is not just the law but the right thing to do. It is a continual process and starts with deliberate planning. Always be alert to ways to protect our environment during training and missions. In doing so, you will contribute to the sustainment of our training resources while protecting people and the environment from harmful effects. Refer to the current Environmental Considerations manual and the current GTA Environmental-related Risk Assessment card.

Safety: In a training environment, leaders must perform a risk assessment in accordance with current Risk Management Doctrine. Leaders will complete the current Deliberate Risk Assessment Worksheet in accordance with the TRADOC Safety Officer during the planning and completion of each task and sub-task by assessing mission, enemy, terrain and weather, troops and support available-time available and civil considerations, (METT-TC). Note: During MOPP training, leaders must ensure personnel are monitored for potential heat injury. Local policies and procedures must be followed during times of increased heat category in order to avoid heat related injury. Consider the MOPP work/rest cycles and water replacement guidelines IAW current CBRN doctrine. Everyone is responsible for safety. A thorough risk assessment must be completed prior to every mission or operation.

Prerequisite Individual Tasks: None
Supporting Individual Tasks: None
Supported Individual Tasks: None
Supported Collective Tasks: None

Knowledges:

Knowledge ID	Knowledge Name
113-K-10107	Familiarization with router fundamentals
113-K-10024	router and LAN security, routing protocols, LAN/WAN topologies, LAN/WAN protocols
113-K-10113	Knowledge of routers
113-K-10023	knowledge of basic network concepts, router concepts, router command line interface knowledge
113-K-10070	Familiarization with TCP/IP subnetting/planning

Skills:

Skill ID	Skill Name
113-S-10124	Explain the difference between local and wide area networks
2	Basic knowledge of Networking
113-S-10111	Explain computing/networking hardware and software architecture
113-S-10094	Interpret basic networking terminology
011-529S	Ability to use a computer
S0842	Operate personal computer
805C-S-0214	Ability to use standard computer keyboard
113-S-10028	Configure Hardware

ICTL Data: None